			jacquard i see. Desi will help k • 4.1-ou • Flat kr • 3-butto buttons oi • Open l Due to thu special ca process. CARE IN: Machine V Softener. Dry Low.	In the and breathable, the texture. But the besigned with moisture- keep you cool and durce, 100% polyester it collar on placket with pear on placket with pear on placket with pear on white hem sleeves are must be taken the structions Wash Cold With Like Only Non-Chlorine Remove Promptly. Constructions Structure of the structur	t part comes from v wicking performan ry. Ir lized smoke tone b olyester performand broughout the scree e Colors. Do Not U Bleach, When Nee Cool Iron, If Necess	what you can't nce, this shirt buttons; white nce fabrics, en printing Use Fabric eded. Tumble		front back
			special ca process. CARE IN Machine V Softener. Dry Low.	are must be taken the sTRUCTIONS Wash Cold With Lik Only Non-Chlorine Remove Promptly. (e Colors. Do Not U Bleach, When Nee Cool Iron, If Necess	en printing Jse Fabric eded. Tumble		back
OW TO MEASURE			Tips For E	Effectively Screen P				
					rinting Polyester Fa	abrics		
Chest		CHEST WIDTH Measure under the a with arms down, kee			est			
ZE CHART		1	1	1.	1	1	1	
	S 2-34	S 35-37	M 38-40	L 41-43	XL 44-46	2XL 47-49	3XL 50-53	4XL 54-57
							0000	
utumn Orange Black	Green	n Glen Grey Smoke	e Hyper Blue	Ocean Blue	Rich Red	True Navy	Vine Green	Violet Purple White